

VCDS
Windows Based VAG/VAS Emulator
Version: Release 12.12.0
www.Ross-Tech.com

Dealer/Shop Name:
Workshop Code: 000 00000

Diagnostic Trouble Code Report
Friday, 22, October, 2021, 13:46:22:62939

VIN: License Plate:
Mileage: Repair Order:

Control Module Part Number: 4F0 910 852 HW: 4F0 905 852 B
Component and/or Version: FBSAUDIC6 ELV H31 0240
Software Coding: 0000131
Work Shop Code: WSC 02323 785 00200
VCID: E3C5C90722A0E306691-80B6
Additional Info: 4F0910131E FBSAUDIC6 EZS H46 0080
Additional Info: Geraet 00200

1 Fault Found:

01176 - Key

004 - No Signal/Communication - Intermittent

Freeze Frame:

Fault Status: 00100100
Fault Priority: 2
Fault Frequency: 12
Reset counter: 124
Mileage: 188008 km
Time Indication: 0
Date: 2021.10.22
Time: 13:04:47