Car data

11:37	22.09.2015

VIN Number	**WV2ZZZ2KZ9X014079**	*Engine Code*	**BLS**
Sales Type	**2KBD42**	*Transmission Code*	**JCS**
Model Year	**2009**	*Finaldrive Ident*	**5S**
Model	**CA**	*Interior Trim Code*	**EN**
Model Designation	**caddy life**	*Roof Color*	**8E**
Date of Productio	**18.06.2008**	*Exterior Color/Paint Code*	**8E/A7W**
Order Number			

PR Numbers

A9J	**Window van Comfort**
B01	**Type approval Germany**
B0A	**Component parts set without country-specific design requirement**
C20	**Operating permit, alteration**
CT7	**Alloy wheels 6J x 15**
D3W	**4-cyl. turbo diesel engine 1.9 L/77 kW TDI with pump-jet injection system Base engine is T71/TG0/TD0/T5X**
E0A	**No special edition**
F0A	**No special purpose vehicle, standard equipment**
G0C	**5-speed manual transmission**
HD2	**Tires 195/65 R15 91T**
J0N	**Battery 330 A (61 Ah)**
K4B	**Window van**
L0L	**Left-hand drive vehicle**
L21	**Suspension range 21 installation control only, no requirement forecast**
N0L	**Fabric seat covering**
NG0	**Without top carrier**
NY0	**Standard battery/alternator capacity**
QC1	**Dark tinted glass in rear seat area heat-insulating glass in front area**
QE1	**Tray areas package 1**
QG1	**Service interval prolongation**
QN1	**Drawer under left front seat**
QV0	**W/o TV reception/digital radio reception**
R31	**Radio system "RCD 300" with six speakers**
S1V	**Varying installation**
TG0	**4-cylinder diesel engine 1.9 L unit 03G.6**
U5A	**Instrument insert, km/h speedometer**
UF0	**Without electric interface**
V0A	**Tires w/o specification of tire brand**
WF2	**Package for Germany**
Z0C	**Team Caddy**
Z1C	**Exterior**
Z3B	**Cool and Sound**
ZP4	**Diesel particulate filter (DPF)**
0E1	**Short wheelbase**

Car data

11:37	22.09.2015

PR Numbers

0EJ	Installation differentiation for transmission MQ 250 vehicle components
0HD	Vehicle class differentiation 2K0
0J2	Standard payload
0NB	Nameplate set in base trim
0VC	Information kit in German
0Y1	Standard climatic zones
0YA	Weight range 1 installation control only, no requirement forecast
1AT	Electronic stabilization program (ESP)
1BA	Standard suspension/shock absorption
1C1	Antifreeze up to -25 degree celsius tolerance up to -30 degree C
1D0	Without trailer hitch
1EX	Spezielles Typschild für EG
1G8	Breakdown set
1HZ	Labels without country group
1N1	Power steering
1NL	Covers for alloy wheels
1PA	Standard wheel bolts
1T0	Without first aid kit and warning triangle
1X0	Front wheel drive
1Z0	Initial standard fuel filling
1ZE	Disc brakes, front (Geomet D)
2E2	15-inch chassis
2G2	W/o insert for the filling up (diesel) without fluorination (not RME resistant)
2JG	Body-colored bumpers
2KW	Labels/plates in German, French, and Dutch
2PG	Steering wheel
2V1	Dust and pollen filter
3B4	Child seat anchor for child seat system ISOFIX
3CA	Without partition
3D6	Center console
3FA	Without roof insert (standard roof)
3H0	Without backrest release for front seats
3HA	Without leather parts scope
3J7	Articulated and height-adjustable headrests for front seats
3L1	Manual height adjustment for left front seat
3LE	Door and side trim panel
3NM	Rear seat bench/backrest, split folding
3RC	Trunk lid with window aperture
3SF	Comfort seat, front right
3TF	Comfort seat, front left
3U1	Foldable trunk cover
4A0	Without seat heater

Car data

11:37	22.09.2015

PR Numbers

4B1	Protective side molding
4DE	Fixed side window in passenger compartment front left
4EM	Sliding window in passenger compartment front right
4FH	Fixed side window in load/passenger compartment left
4GF	Windshield in heat-insulating glass
4H1	Child lock in passenger compartment
4HH	Heated rear window
4JH	Fixed side window in load/passenger compartment right
4K3	Radio remote controlled central locking operated from inside and safe securing
4L6	Breakaway interior rear view mirror, automatically dimming
4N2	Standard dashboard
4R4	Power windows with comfort operation and circuit breaker
4SA	Without left vanity mirror
4TC	Right vanity mirror with cover
4UF	Driver's and front passenger air bag with front passenger air bag deactivation
4X1	Side air bag front
5AD	Carpet floor covering in cab
5BF	Carpet floor covering in passenger compartment
5CH	Roof interior trim, comfort molded headlining in cab and passenger compart.
5D1	Carrier frequency 433.92 MHz-434.42 Mhz
5DD	Comfort side panel trim in passenger compartment
5K5	Transit coating film with additional transport protection measures
5Q2	Sliding door left in load/passenger compartment
5R2	Sliding door right in load/passenger compartment
5RQ	Right exterior mirror: convex
5SL	Left exterior mirror: aspherical
5TC	Without decorative inserts
6EA	Without additional side body covers (stone guard)
6FB	Body-colored exterior mirror housings
6P9	Rear license plate bracket
6XN	Exterior mirrors: electrically adjustable, separately heated
7A0	Without CD changer/CD player
7AA	Electronic vehicle immobilization device
7B2	12-volt socket in luggage boot
7GG	Emission standard EU4 DPF
7Q0	Without navigation device
7QA	Without CD/DVD for navigation

Car data

11:37	22.09.2015

PR Numbers

7X0	Without park distance control
8AE	Radio "RCD310 MP3"
8BG	Twin-headlight for driving on the right, with integrated high beam
8GU	Alternator 140 A
8K3	Separate daytime running lights with low beam assistant and "Coming Home" feature
8M1	Rear window wiper and washer system with intermittent control
8N3	Windshield wiper intermittent control with rain sensor
8Q1	Headlight-range adjustment
8QE	Key for locking system with remote control
8RL	6 speakers (passive)
8T0	Without cruise control system (CCS)
8TC	Rear fog light for driving on the right
8W0	Without washer fluid level indicator
8WD	Integrated front fog light
8X0	Without headlight washer system
8Y0	Single-tone horn
8Z5	Not hot country
9AD	Climatronic, free of cfc
9CC	Two standard interior lights in passenger/load compartment
9JA	Non-smoking package
9M0	Without auxiliary/parking heater
9P0	Without seat belt reminder
9Q0	Without multi-function display/ on-board computer
9T0	Without heated washer nozzles
9W0	W/o car phone preparation/installation
9WL	Multimedia socket for external audio source